

RGB
RGB atmosphere light bar/
battery indicator light

TYPE-C
Type-C Interface

2.4G
Mode switch left BT/
wired/right 2.4G

USB
USB receiver

CAP
CAP capitalization
indication

WIN
Lock WIN indicator
light up white



X75 RHINO

TRI MODE | MECHANICAL KEYBOARD

	Light brightness +		Android		Atmosphere Lighting effect adjustment
	Light brightness -		Windows		Long press for 3 s to restore factory defaults
	Light effect speed -		MAC		Light color switching
	Light effect speed +		Light mode switching		Atmosphere Light Speed Adjustment

BT MODE



1. Switch to BT mode



2. Press the key combination to switch to BT 1, about 3 seconds until the blue light flashes quickly to enter pairing



3. Search for the pairing name; X75 RHINO 5.0 or X75 RHINO 3.0 the connection is successful, the blue light is always on for 2s and then off

Note: The connection method for Bluetooth 2 and Bluetooth 3 is the same as Bluetooth 1. Bluetooth 2 can be connected by pressing the combination key [FN+2 @], while Bluetooth 3 can be connected by pressing the combination key [FN+3 #]; In Bluetooth reconnection mode, the blue light will turn on for 3 seconds and then turn off.

2.4 G MODE 1



1. Switch to 2.4G mode



2. Take out the USB receiver



3. Insert it into the USB port of your computer to use


2.4 G MODE 2



1. Press and hold the key combination for about 3s until the green light flashes slowly, then it will enter the code pairing



2. Take out the USB receiver



3. Insert the USB receiver into the USB port


WIRED MODE



1. Switch to Wired mode



2. Insert one end of the standard USB cable Type-C into the corresponding port on the keyboard



3. Insert one end of the cable USB head into the computer USB port